


**“AIR TOP ITALIA”** | by **H PARTS**

Automotive Solutions



**3Active**

ANTIBACTERIAL CABIN FILTERS

# HPARTS

Automotive Solutions

# HPARTS

Automotive Solutions

Air Top Italia has recently become part of the Holding parts Group, a large new company operating in the Automotive Aftermarket, who focuses on successful Italian companies with great international vocation: a new challenge that will lead to the growth of Air Top Italia and a further improvement of production, logistics, a commercial and distribution model that is already well established.


Holding Parts aims to bring together Italian excellences in the supply chain for spare parts in the automotive sector dedicated to cars, heavy vehicles and agricultural vehicles, with the aim of becoming a point of reference in the long term to make the most out of the significant potential for growth through the various synergies resulting from bringing together different production and distribution companies, both nationally and internationally.

Holding Parts was born from the vision of Holding Industriale SpA (Hind) together with RGR & CO. (a manifestation of modern-day management) and a Club Deal made up of Italian and international entrepreneurs.

 **“AIR TOP ITALIA”**  **GPC**

**Blue is the way to go**

# 3Active



3Active cabin filters are perfect because they provide drivers with the maximum protection from viruses and bacteria in their own cabin and allows professionals to have spares to offer a suitable and efficient product, in line with the needs of its customers.

# **Wide range**


With over 100 codes guaranteeing 90% coverage of European vehicles in circulation, Air Top Italia allows you to offer to your customers the best Antibacterial filter for basically every vehicle on the road.

# **Consumer health**

Thanks to the use of antibacterial filters 3Active, whose raw material is 100% tested at every production cycle, ensure the best possible protection against viruses and bacteria to car users.

# **Grow your business**

The price range of the best antibacterial filter on the market guarantees the whole entire distribution chain higher revenues with a minimum investment of the driver compared to the benefits obtained.



**Block 99%  
of pathogens.**

KEEPS  
**BACTERIA**  
AND  
**VIRUSES**  
AWAY

**3Active** is the cabin filter that blocks 99% of pathogens.

From the laboratories of Air Top Italia, a leader in the cabin filtration sector, comes **3Active**, the first filter on the market capable of blocking 99% of molds and bacteria directed into the cabin through the ventilation system. Thanks to the innovative NON WOVEN non-woven fabric FRESH, the **3Active** filter is able to attract the cell membrane by blocking pathogens without the commitment of any chemical substance, thus ensuring the cleanliness and health of the passenger compartment.

**ANTI-ALLERGENS, ANTIBACTERIAL, ANTPOLLIN, ANTISMOG**

**3Active**

## Are you sure that your car interior is fit for its purpose?

There are probably few people who ask themselves questions about what happens inside their car and, more specifically, on what enters their car interior through the air conditioning vents. Air which enters into the car at high speed transports **millions of pathogenic agents**, including **contagious bacteria and poisonous fungi**. Most people tend to underestimate the impact of such a bombardment, but it could, in extreme cases, transform the interior of the vehicle into fertile ground for germs and bacteria.

This is why **it is important to install a high-quality filter**, capable of **blocking pathogenic agents** and trapping them within an arid and hostile environment.

**That is why you need 3Active.**

## 3Active: a triple-action filter


From the laboratories of Air Top Italia, a 100% Italian company and leader in the vehicle interior filtration market, comes a new bio-barrier, a completely natural membrane capable of **stopping 99% of the pathogenic agents** which would otherwise reach the interior of the car through the ventilation system, preventing their spread and holding them in a hostile environment. We are talking about **the new 3Active car interior filter** which, thanks to its highly porous active carbon, also forms a **barrier against harmful gases and allergens**, protecting the air vents and **guaranteeing a comfortable and pleasant journey** for everyone who suffers from seasonal allergies.



## Non Woven Fresh: a fibre which traps

The key to 3Active's high performance is **NON WOVEN FRESH**, an innovative unwoven fabric which is **entirely free of chemical substances**, made of viscose, cellulose and polyester and covered with a polyamidoamine derivative. This gives the structure a positive charge which is able to attract the bacterial membrane.

**The pathogenic agents are thus blocked** and they cannot find conditions which are favourable to their development. The filter is therefore left in excellent condition, which strongly favours the cleanliness and hygiene of the vehicle interior.



## 3Active: blocks dozens of species of fungi and bacteria

The car interior air filters have a specific protective purpose, but they must be adequately and regularly replaced. If they are left too long without being replaced, particulates, pollen, allergens, bacteria and fungi can accumulate in the filter, ready to burst their way into the car and cause some nasty surprises: from a simple 'flu to dangerous forms of salmonellosis or even Legionella! That is why it is so important to have an air filter for the interior of your vehicle, and this is why you should choose 3Active over and above all the other filters on the market. It is simply the most powerful and the most complete of all of them.

Filter comparison	ANTI-POLLEN FILTER	CARBON FILTER	3Active
Protects the air conditioning system	✓	✓	✓
Avoid the windows misting up	✓	✓	✓
Traps pollen and particulates (PM10)	✓	✓	✓
Removes odours		✓	✓
Traps harmful gases (ozone, exhaust fumes...)		✓	✓
Traps particulates (PM2.5)		✓	✓
Protects the respiratory tract		✓	✓
Prevents the formation of fungi and bacteria*			✓
It is effective against allergens and bacteria			✓



\*Micrococcus sp., Staphylococcus epidermidis 1, Enterobacter agglomerans 1, Acinetobacter calcoaceticus 1, Staphylococcus aureus (pigmented), Staphylococcus aureus (non pigmented), Klebsiella pneumoniae ATCC4352, Pseudomonas aeruginosa, Pseudomonas aeruginosa PRD-10, Streptococcus faecalis, Pseudomonas aeruginosa 1, Escherichia coli ATCC 25266, Escherichia coli 1, Proteus mirabilis, Citrobacter diversus 1, Salmonella typhosa, Proteus mirabilis 1, Salmonella choleraesuis, Corynebacterium bovis, Mycobacterium smegmatis, Mycobacterium tuberculosis, Brucella canis, Brucella abortus, Brucella suis, Streptococcus mutans, Bacillus subtilis, Bacillus cereus, Clostridium perfringens, Haemophilus suis, Lactobacillus casei, Leuconostoc lactis, Listeria monocytogenes, Propionibacterium acnes, Proteus vulgaris, Pseudomonas cepacia, Pseudomonas fluorescens, Xanthomonas campestris, Aspergillus niger, Aspergillus fumigatus, Aspergillus versicolor, Aspergillus flavus, Aspergillus terreus, Penicillium chrysogenum, Penicillium albicans, Penicillium citrinum, Penicillium elegans, Penicillium funiculosum, Penicillium humicola, Penicillium notatum, Penicillium variabile, Mucor sp., Trichophyton mentagrophytes, Trichophyton interdigitale, Trichoderma flavus, Chaetomium globosum, Rhizopus nigricans, Cladosporium herbarum, Aureobasidium pullulans, Fusarium nigrum, Fusarium solani, Gliocladium roseum, Oospora lactis, Stachybotrys atra



— Catalogue  
2021

## ALFA ROMEO

ALFA ROMEO 159 05>	<b>3A517</b>
ALFA ROMEO BRERA 06>	<b>3A517</b>
ALFA ROMEO MITO 08>	<b>3A526</b>
ALFA ROMEO SPIDER (939) 06>	<b>3A517</b>
ALFA ROMEO 147 10/00>	<b>3A426</b>
ALFA ROMEO 156 02>	<b>3A426</b>
ALFA ROMEO CROSSWAGON Q4 04>	<b>3A426</b>
ALFA ROMEO GT 02/04>	<b>3A426</b>
ALFA ROMEO SPORTWAGON 02>	<b>3A426</b>
ALFA ROMEO GIULIETTA (940) 10>	<b>3A601</b>

## AUDI

AUDI A1 (8X) 10>	<b>3A646</b>
AUDI A2 (8Z0) 06/00>	<b>3A424</b>
AUDI A3 (8V/8VS) 12>	<b>3A633</b>
AUDI A3 II (8P1/8PA) 05/03>	<b>3A473</b>
AUDI A3 < FG.-NR. 8L V090450 96>	<b>3A329</b>
AUDI A3 FG.-NR. 8L V090451 > 96>	<b>3A390</b>
AUDI A4 (8K, B8) 07>	<b>3A564</b>
AUDI A5 (8T) 07>	<b>3A564</b>
AUDI Q3 (8U) 11>	<b>3A473</b>
AUDI Q5 (8R) 08>	<b>3A564</b>
AUDI TT/TTS (8N3,8N9) 99>	<b>3A390</b>
AUDI TT/TTS (8S) 14>	<b>3A633</b>
AUDI TT/TTS II (8J0) 06>	<b>3A473</b>
AUDI A4 (8H7) 11/04>	<b>3A428</b>
AUDI A4 (B6/8E2, 8E5) 01/01>	<b>3A428</b>
AUDI Q7 (4L) 06>	<b>3A476</b>
AUDI A6 (4G2/4G5) 11>	<b>3A605</b>
AUDI A4(8W2) 15>	<b>3A667</b>

## BMW

BMW SERIE 1 (F20/F21) 11>	<b>3A621</b>
BMW SERIE 1 (E81/E82/E87/E88) 04>	<b>3A515</b>
BMW SERIE 2 (F22/F23) 14>	<b>3A621</b>
BMW SERIE 3 (E46) 98 >	<b>3A403</b>

BMW SERIE 3 (E46 COMPACT) 01 >	<b>3A403</b>
BMW SERIE 3 (E90/E91/E92/E93) 05>	<b>3A515</b>
BMW SERIE 3 (F30/F31) 12>	<b>3A621</b>
BMW SERIE 3 GT (F34) 13>	<b>3A621</b>
BMW SERIE 4 (F32/F33/F36/F82) 13>	<b>3A621</b>
BMW X1 (E84) 09 >	<b>3A515</b>
BMW X3 (E83) 12/03>	<b>3A403</b>
BMW i3 (I01)13>	<b>3A642</b>
BMW SERIE 5 (F10/F11/F18) 10>	<b>3A590</b>
BMW SERIE 5 E 60 / E 6109/ 03>	<b>3A501</b>
<b>CADILLAC</b>	
CADILLAC SRX II 09>	<b>3A577</b>
CADILLAC BLS 06>	<b>3A421</b>
CADILLAC CTS II 14>	<b>3A636</b>
<b>CHRYSLER</b>	
CHRYSLER YPSILON 11>	<b>3A626</b>
CHRYSLER SEBRING 07>	<b>3A549</b>
CHRYSLER DELTA 11>	<b>3A451</b>
<b>CITROËN</b>	
CITROEN C1 II (B4) 14>	<b>3A653</b>
CITROEN C2 09/03>	<b>3A446</b>
CITROEN C3 / C3 PLURIEL 02>	<b>3A446</b>
CITROEN C3 II (A51) 09>	<b>3A540</b>
CITROEN C3 MULTISPAZIO/PICASSO 09>	<b>3A446</b>
CITROEN C4 04>	<b>3A446</b>
CITROEN C4 CACTUS 14>	<b>3A540</b>
CITROEN C4 II (B7) 10>	<b>3A446</b>
CITROEN C4 SEDAN 13>	<b>3A446</b>
CITROEN DS3 10>	<b>3A540</b>
CITROEN DS4 11>	<b>3A446</b>
CITROEN NEMO (RHD) 08>	<b>3A526</b>
CITROEN JUMPER III / RELAY III 06>	<b>3A542</b>
CITROEN JUMPY II 07>	<b>3A555</b>
CITROEN C3AIRCROSS 17>	<b>3A675</b>
CITROEN C4 AIRCROSS 12>	<b>3A474</b>

CITROEN C512/ 04>	<b>3A512</b>
CITROEN XSARA PICASSO02/ 00>	<b>3A419</b>
CITROEN BERLINGO II (B9)08>	<b>3A554</b>
CITROEN C 106/ 05>	<b>3A516</b>
<b>DACIA</b>	
DACIA DUSTER II 10>	<b>3A480</b>
DACIA LOGAN II 13>	<b>3A629</b>
DACIA SANDERO 08>	<b>3A480</b>
DACIA SANDERO II 13>	<b>3A629</b>
DACIA DOKKER 12>	<b>3A640</b>
<b>DAEWOO (CHEVROLET)</b>	
DAEWOO (CHEVROLET) AVEO II 11>	<b>3A577</b>
DAEWOO (CHEVROLET) COBALT 14>	<b>3A577</b>
DAEWOO (CHEVROLET) CRUZE 09>	<b>3A577</b>
DAEWOO (CHEVROLET) MALIBU 12>	<b>3A577</b>
DAEWOO (CHEVROLET) ORLANDO 11>	<b>3A577</b>
DAEWOO (CHEVROLET) TRAX 13>	<b>3A577</b>
DAEWOO (CHEVROLET) VOLT 11>	<b>3A577</b>
<b>DAIHATSU</b>	
DAIHATSU CHARADE II 11>	<b>3A528</b>
DAIHATSU TERIOS 06>	<b>3A472</b>
<b>DODGE</b>	
DODGE AVENGER 07>	<b>3A549</b>
DODGE CALIBER 06>	<b>3A549</b>
DODGE JOURNEY 08>	<b>3A549</b>
<b>FERRARI</b>	
FERRARI CALIFORNIA 08>	<b>3A517</b>
FERRARI F12 12>	<b>3A517</b>
FERRARI FF 11>	<b>3A517</b>
FERRARI 458 09>	<b>3A635</b>
FERRARI 612 SCAGLIETTI 04>	<b>3A509</b>
<b>FIAT</b>	
FIAT 500 (150) 07>	<b>3A487</b>
FIAT 500 (150) 09/11>	<b>3A626</b>
FIAT DOBLO' (223) 01>	<b>3A436</b>

FIAT DOBLO' / DOBLO' CARGO RHD 10>	<b>3A526</b>
FIAT FIORINO (RHD) 08>	<b>3A526</b>
FIAT GRANDE PUNTO (199) / EVO 05>	<b>3A526</b>
FIAT IDEA 04>	<b>3A436</b>
FIAT PANDA II (169A) 09/03>	<b>3A487</b>
FIAT PANDA III 12>	<b>3A626</b>
FIAT PUNTO II (188/188AX) 01>	<b>3A436</b>
FIAT PUNTO III (188/2003) 03>	<b>3A436</b>
FIAT QUBO (225) (RHD) 08>	<b>3A526</b>
FIAT CROMA II (194) 05>	<b>3A421</b>
FIAT DUCATO 2007 (250/251) 06>	<b>3A542</b>
FIAT FREEMONT 11>	<b>3A549</b>
FIAT SCUDO II (272) 07>	<b>3A555</b>
FIAT 500L 12>	<b>3A637</b>
FIAT 500X 15>	<b>3A637</b>
FIAT SEDICI (189) 06>	<b>3A472</b>

## FORD

FORD FOCUS IV 18>	<b>3A679</b>
FORD KUGA III 19>	<b>3A679</b>
FORD B-MAX 12>	<b>3A583</b>
FORD C-MAX / GRAND C-MAX 11>	<b>3A622</b>
FORD C-MAX 07>	<b>3A491</b>
FORD C-MAX II / GRAND C-MAX 10>	<b>3A491</b>
FORD ECOSPORT 14>	<b>3A583</b>
FORD FIESTA VI 08>	<b>3A583</b>
FORD FOCUS C-MAX 03>	<b>3A491</b>
FORD FOCUS III 11>	<b>3A622</b>
FORD GALAXY II 06>	<b>3A491</b>
FORD KA II 08>	<b>3A487</b>
FORD KUGA 08>	<b>3A491</b>
FORD KUGA II 13>	<b>3A622</b>
FORD MONDEO IV 07>	<b>3A491</b>
FORD S-MAX 06>	<b>3A491</b>
FORD TOURNEO CONNECT II 13>	<b>3A622</b>
FORD TRANSIT / TOURNEO COURIER (C4A) 14>	<b>3A583</b>
FORD TRANSIT CONNECT II (CHC) 13>	<b>3A622</b>

FORD TRANSIT 13>	<b>3A639</b>
FORD TRANSIT 2007 06>	<b>3A630</b>
FORD EDGE (CDQ) 15>	<b>3A662</b>
FORD FIESTA V 02>	<b>3A468</b>
FORD FUSION/FUSION PLUS 10/02>	<b>3A468</b>
<b>HONDA</b>	
HONDA ACCORD IX 08>	<b>3A497</b>
HONDA JAZZ 02>	<b>3A472</b>
HONDA JAZZ III (GE) 08>	<b>3A596</b>
HONDA JAZZ IV (GK) 15>	<b>3A596</b>
<b>HYUNDAI</b>	
HYUNDAI I30 / I30 CW (FD) 07>	<b>3A546</b>
HYUNDAI IX35 (LM) 10>	<b>3A550</b>
HYUNDAI TUCSON 2.0 CRDI 140CV 06>	<b>3A550</b>
HYUNDAI TUCSON II 15>	<b>3A550</b>
HYUNDAI IX20 10>	<b>3A603</b>
HYUNDAI ACCENT IV 11>	<b>3A507</b>
HYUNDAI ELANTRA II (XD2) 06>11	<b>3A648</b>
<b>JAGUAR</b>	
JAGUAR E-PACE 17>	<b>3A553</b>
<b>JEEP</b>	
JEEP COMPASS 06>	<b>3A549</b>
JEEP PATRIOT 06>	<b>3A549</b>
JEEP COMPASS III 17>	<b>3A637</b>
JEEP RENEGADE (BU) 14>	<b>3A637</b>
<b>KIA</b>	
KIA CEE'D 07>	<b>3A546</b>
KIA PRO-CEE'D 07>	<b>3A546</b>
KIA SPORTAGE III 10>	<b>3A550</b>
KIA SPORTAGE IV 16>	<b>3A550</b>
KIA VENGA (YN) 10>	<b>3A603</b>
<b>LANCIA</b>	
LANCIA FLAVIA 12>	<b>3A549</b>
LANCIA MUSA 09/04>	<b>3A436</b>
LANCIA YPSILON 03>	<b>3A436</b>

LANCIA YPSILON II (846) 09/11>	<b>3A626</b>
LANCIA YPSILON II (846) 10>	<b>3A487</b>
<b>LAND ROVER</b>	
LAND ROVER RANGE ROVER IV (LG) 13>	<b>3A528</b>
LAND ROVER RANGE ROVER SPORT II (LW) 13>	<b>3A528</b>
LAND ROVER DISCOVERY SPORT 14>	<b>3A553</b>
LAND ROVER FREELANDER II 07>	<b>3A553</b>
LAND ROVER RANGE ROVER EVOQUE 11>	<b>3A553</b>
<b>LEXUS</b>	
LEXUS CT 11>	<b>3A528</b>
LEXUS GS 300 III 05>	<b>3A528</b>
LEXUS IS 200 III 05>	<b>3A528</b>
LEXUS LFA 11>	<b>3A528</b>
LEXUS NX 14>	<b>3A528</b>
LEXUS RX 450H 09>	<b>3A528</b>
LEXUS GX02>09	<b>3A511</b>
<b>MAZDA</b>	
MAZDA 2 (DY)02/03>	<b>3A478</b>
<b>MERCEDES</b>	
MERCEDES BENZ CLA (C117) 13>	<b>3A623</b>
MERCEDES BENZ CLASSE A (W169) 04>	<b>3A508</b>
MERCEDES BENZ CLASSE A (W176) 12>	<b>3A623</b>
MERCEDES BENZ CLASSE B (W245) 05>	<b>3A508</b>
MERCEDES BENZ CLASSE B (W246) 11>	<b>3A623</b>
MERCEDES BENZ GLA (X156) 13>	<b>3A623</b>
MERCEDES CITAN (W415) 12>	<b>3A581</b>
MERCEDES BENZ CLASSE C (W203/C203/T203) 05/00>	<b>3A416</b>
MERCEDES BENZ CLASSE C (W205/S205)14>	<b>3A631</b>
MERCEDES BENZ CLASSE C W/S 20515>	<b>3A665</b>
MERCEDES BENZ CLASSE E (W211)02>	<b>3A459</b>
MERCEDES BENZ CLASSE G (W461/463)98>	<b>3A423</b>
MERCEDES BENZ SPRINTER (NCV2)09/03>	<b>3A494</b>
MERCEDES CLASSE VII (447) 14>	<b>3A659</b>
<b>MINI</b>	
MINI CLUBMAN 11/06>	<b>3A548</b>

MINI COOPER II (R56) 11/06>	<b>3A548</b>
MINI COUNTRYMAN 06>	<b>3A548</b>
MINI ONE II (R56) 11/06>	<b>3A548</b>
<b>NISSAN</b>	
NISSAN MICRA (K12) 03>	<b>3A480</b>
NISSAN MICRA (K13) 10>	<b>3A600</b>
NISSAN NOTE (E12) 13>	<b>3A600</b>
NISSAN NOTE 06>	<b>3A480</b>
NISSAN PRIMASTAR II 14>	<b>3A591</b>
NISSAN PULSAR 14>	<b>3A649</b>
NISSAN QASHQAI II 14>	<b>3A649</b>
NISSAN QASHQAI 07>	<b>3A566</b>
NISSAN X-TRAIL II (T31) 07>	<b>3A566</b>
NISSAN NV400 11>	<b>3A581</b>
NISSAN JUKE 10>	<b>3A594</b>
<b>OPEL</b>	
OPEL ADAM 12>	<b>3A526</b>
OPEL AGILA II 08>	<b>3A573</b>
OPEL AMPERA 11>	<b>3A577</b>
OPEL ASTRA-J 09>	<b>3A577</b>
OPEL CASCADA 13>	<b>3A577</b>
OPEL COMBO-D (X12) RHD 12>	<b>3A526</b>
OPEL COMBO-D (X12) 12>	<b>3A572</b>
OPEL CORSA-D 06>	<b>3A526</b>
OPEL CORSA-E 14>	<b>3A526</b>
OPEL INSIGNIA 08>	<b>3A577</b>
OPEL MERIVA B 10>	<b>3A577</b>
OPEL MOKKA 12>	<b>3A577</b>
OPEL VIVARO B 14>	<b>3A591</b>
OPEL ZAFIRA-C / ZAFIRA TOURER 11>	<b>3A577</b>
OPEL COMBO-B 09/01>	<b>3A421</b>
OPEL CORSA-C 11/00>	<b>3A421</b>
OPEL SIGNUM 03>	<b>3A421</b>
OPEL TIGRA TWIN TOP 07/04>	<b>3A421</b>
OPEL VECTRA-C 02>	<b>3A421</b>
OPEL MOVANO B 10>	<b>3A581</b>

OPEL ASTRA K 15>	<b>3A636</b>
OPEL MERIVA B 07/12>	<b>3A636</b>
OPEL AGILA 05/00>	<b>3A413</b>
OPEL MERIVA A 04/03>	<b>3A477</b>
<b>PEUGEOT</b>	
PEUGEOT 1007 05>	<b>3A446</b>
PEUGEOT 108 14>	<b>3A653</b>
PEUGEOT 2008 13>	<b>3A540</b>
PEUGEOT 207 06>	<b>3A540</b>
PEUGEOT 208 12>	<b>3A540</b>
PEUGEOT 307 01>	<b>3A446</b>
PEUGEOT 308 07>	<b>3A446</b>
PEUGEOT 408 12>	<b>3A446</b>
PEUGEOT BIPPER (RHD) 08>	<b>3A526</b>
PEUGEOT RCZ 10>	<b>3A446</b>
PEUGEOT BOXER III 06>	<b>3A542</b>
PEUGEOT EXPERT II 07>	<b>3A555</b>
PEUGEOT 308 II 13>	<b>3A647</b>
<b>PORSCHE</b>	
PORSCHE MACAN 14>	<b>3A564</b>
<b>RENAULT</b>	
RENAULT CAPTUR 13>	<b>3A629</b>
RENAULT CLIO III 05>	<b>3A480</b>
RENAULT CLIO IV 12>	<b>3A629</b>
RENAULT MODUS / GRAND MODUS 04>	<b>3A480</b>
RENAULT SCENIC III 09>	<b>3A591</b>
RENAULT TRAFIC III 14>	<b>3A591</b>
RENAULT TWINGO II 07>	<b>3A480</b>
RENAULT TWINGO III 14>	<b>3A654</b>
RENAULT WIND 10>	<b>3A480</b>
RENAULT KANGOO II / KANGOO BE BOP 08>	<b>3A581</b>
RENAULT MASTER IV 10>	<b>3A581</b>
RENAULT MEGANE CC 10>	<b>3A582</b>
RENAULT MEGANE III 08>	<b>3A582</b>
RENAULT MEGANE II 10/02>	<b>3A470</b>
RENAULT SCENIC III 07/03>	<b>3A482</b>
<b>SAAB</b>	
SAAB 9-5 II 10>	<b>3A577</b>

## SANTANA

SANTANA 300 / 350 98>	<b>3A540</b>
-----------------------	--------------

## SEAT

SEAT ALHAMBRA II (71) 10>	<b>3A473</b>
SEAT ALTEA 04>	<b>3A473</b>
SEAT CORDOBA III 10/02>	<b>3A424</b>
SEAT IBIZA IV 01>	<b>3A424</b>
SEAT IBIZA V 10>	<b>3A646</b>
SEAT LEON II 05>	<b>3A473</b>
SEAT LEON III 12>	<b>3A633</b>
SEAT TOLEDO III 04>	<b>3A473</b>
SEAT TOLEDO IV 12>	<b>3A646</b>
SEAT EXEO 09>	<b>3A428</b>
SEAT MII 11>	<b>3A624</b>

## ŠKODA

SKODA CITIGO 11>	<b>3A624</b>
SKODA FABIA II (5J6,5J9) 10>	<b>3A646</b>
SKODA FABIA III (NJ3,NJ5) 14>	<b>3A646</b>
SKODA OCTAVIA II 04>	<b>3A473</b>
SKODA OCTAVIA III 13>	<b>3A633</b>
SKODA PRAKTIK 10>	<b>3A646</b>
SKODA RAPID (NH3) 12>	<b>3A646</b>
SKODA ROOMSTER 10>	<b>3A646</b>
SKODA SUPERB II (3T) 08>	<b>3A473</b>
SKODA SUPERB III (3V) 15>	<b>3A633</b>
SKODA YETI (5J) 09>	<b>3A473</b>

## SMART

SMART FORFOUR (453) 14>	<b>3A654</b>
SMART FORTWO (453) 14>	<b>3A654</b>
SMART FORTWO 07>	<b>3A551</b>

## SUBARU

SUBARU LEGACY IV 09>	<b>3A528</b>
SUBARU OUTBACK III 09>	<b>3A528</b>
SUBARU TREZIA 11>	<b>3A528</b>
SUBARU LEGACY III 08>	<b>3A414</b>
SUBARU OUTBACK II 08>	<b>3A414</b>
SUBARU BRZ 12>	<b>3A472</b>

## SUZUKI

SUZUKI SPLASH 08>	<b>3A573</b>
SUZUKI IGNIS III16>	<b>3A669</b>
SUZUKI JIMNY98>	<b>3A547</b>
SUZUKI VITARA15>	<b>3A656</b>
SUZUKI SWIFT 05>	<b>3A472</b>
SUZUKI SX4 06>	<b>3A472</b>

## TOYOTA

TOYOTA RAV 4 09/00>	<b>3A414</b>
TOYOTA YARIS (JAPANESE PROD.) 99>	<b>3A414</b>
TOYOTA PROACE 13>	<b>3A555</b>
TOYOTA AURIS I (E150) 07>	<b>3A528</b>
TOYOTA AURIS II (E180) 12>	<b>3A528</b>
TOYOTA AVENSIS III 09>	<b>3A528</b>
TOYOTA AYGO II 14>	<b>3A653</b>
TOYOTA CAMRY 06>	<b>3A528</b>
TOYOTA COROLLA X 07>	<b>3A528</b>
TOYOTA COROLLA XI (E18) 13>	<b>3A528</b>
TOYOTA HI-LUX 05>	<b>3A528</b>
TOYOTA LAND CRUISER (J20) 09>	<b>3A528</b>
TOYOTA RAV 4 II 06>	<b>3A528</b>
TOYOTA RAV 4 IV 12>	<b>3A528</b>
TOYOTA URBAN CRUISER 09>	<b>3A528</b>
TOYOTA VERSO 09>	<b>3A528</b>
TOYOTA YARIS II (XP9) 06>	<b>3A528</b>
TOYOTA YARIS II (XP9) 06>	<b>3A528</b>
TOYOTA YARIS II (XP9) 06>	<b>3A528</b>
TOYOTA YARIS III (XP13) 11>	<b>3A528</b>
TOYOTA COROLLA IX02>	<b>3A457</b>
TOYOTA GT86 12>	<b>3A472</b>

## VOLKSWAGEN

VOLKSWAGEN UP 11>	<b>3A624</b>
VOLKSWAGEN BEETLE (5C) 11>	<b>3A473</b>
VOLKSWAGEN BORA II 12/04>	<b>3A473</b>
VOLKSWAGEN CADDY III (2KA, 2KB, 2KH, 2KJ) 04>	<b>3A473</b>

VOLKSWAGEN CADDY IV (2C) 10>	<b>3A473</b>
VOLKSWAGEN CC (358) 12>	<b>3A473</b>
VOLKSWAGEN EOS 06>	<b>3A473</b>
VOLKSWAGEN FOX 05>	<b>3A424</b>
VOLKSWAGEN GOLF V / GOLF PLUS 11/03>	<b>3A473</b>
VOLKSWAGEN GOLF VI / GOLF PLUS (5K1) 08>	<b>3A473</b>
VOLKSWAGEN GOLF VII (5G1/BA5) 11/12>	<b>3A633</b>
VOLKSWAGEN JETTA III (1K2) 05>	<b>3A473</b>
VOLKSWAGEN JETTA IV (162) 11>	<b>3A473</b>
VOLKSWAGEN PASSAT (36) / PASSAT CC (357) 10>	<b>3A473</b>
VOLKSWAGEN PASSAT (3C2) 05>	<b>3A473</b>
VOLKSWAGEN PASSAT (3G2/3G5) 14>	<b>3A633</b>
VOLKSWAGEN POLO IV (9N) 01>	<b>3A424</b>
VOLKSWAGEN POLO V (6R) 09>	<b>3A424</b>
VOLKSWAGEN POLO V (6R) 10>	<b>3A646</b>
VOLKSWAGEN SCIROCCO III (1K3) 08>	<b>3A473</b>
VOLKSWAGEN SHARAN II (7N) 10>	<b>3A473</b>
VOLKSWAGEN TOURAN (1T) 09/03>	<b>3A473</b>
VOLKSWAGEN TOURAN (1T) 09/03>	<b>3A473</b>
VOLKSWAGEN TOURAN (1T) 09/03>	<b>3A473</b>
VOLKSWAGEN VENTO INDIA (602) 10>	<b>3A424</b>

## VOLVO

VOLVO C30 06>	<b>3A510</b>
VOLVO C70 II 05>	<b>3A510</b>
VOLVO S40 04>	<b>3A510</b>
VOLVO S40 II / V40 CROSS COUNTRY 12>	<b>3A622</b>
VOLVO V50 04>	<b>3A510</b>
VOLVO S60 II / V60 10>	<b>3A544</b>
VOLVO S80 II 07>	<b>3A544</b>
VOLVO V70 II 07>	<b>3A544</b>
VOLVO XC60 08>	<b>3A544</b>
VOLVO XC70 II 08>	<b>3A544</b>
VOLVO V40 II / V40 CROSS COUNTRY 12>	<b>3A622</b>
VOLVO S4003/ 03>	<b>3A407</b>

**3Active** technology is available for all **AirTop** brands

# **“AIR TOP ITALIA”** | by **HPARTS** Automotive Solutions



**airtopitalia.com**

Air Top Italia s.r.l.  
Via I° Maggio, 282  
41019 Soliera (MO) - ITALY

P.IVA: 01967720366  
Registro imprese: R.E.A. MO n. 255648  
Capitale sociale: Euro 96.000,00 i.v.

Tel. +39.(0)59.565435  
Fax. +39.(0)59.565657  
info@airtopitalia.eu

Single shareholder company subject to management and coordination by Holding Industriale S.p.A.



# **“AIR TOP ITALIA”**

---

**by HPARTS**

Automotive Solutions

[airtopitalia.com](http://airtopitalia.com) | [holdingparts.com](http://holdingparts.com)